```
FILE 'CAPLUS, WPIX' ENTERED AT 10:22:52 ON 07 JUN 2010
            44 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L15
               (DIMER DIOL)) (3A) ?ACRYL?)
            26 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L16
               (DIMER DIOL)) (3A) ?ACRYL?)
    TOTAL FOR ALL FILES
            70 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L17
               (DIMER DIOL)) (3A) ?ACRYL?)
L18
            21 SEA SPE=ON ABB=ON PLU=ON L15 AND (COAT? OR APPL?)
            18 SEA SPE=ON ABB=ON PLU=ON L16 AND (COAT? OR APPL?)
L19
     TOTAL FOR ALL FILES
L20
            39 SEA SPE=ON ABB=ON PLU=ON L17 AND (COAT? OR APPL?)
               D 1-39 ALL, FULL RN
             1 SEA SPE=ON ABB=ON PLU=ON L15 AND (FLATTING OR FLATTED OR
L21
               MATTE OR MATTED OR MATTING)
             1 SEA SPE=ON ABB=ON PLU=ON L16 AND (FLATTING OR FLATTED OR
L22
               MATTE OR MATTED OR MATTING)
    TOTAL FOR ALL FILES
L23
             2 SEA SPE=ON ABB=ON PLU=ON L17 AND (FLATTING OR FLATTED OR
               MATTE OR MATTED OR MATTING)
               D 1-2 ALL, FULL RN
    FILE 'USPATFULL, USPATOLD, USPAT2, EPFULL, PCTFULL' ENTERED AT 10:31:22
    ON 07 JUN 2010
            31 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L24
               (DIMER DIOL)) (3A) ?ACRYL?)
L25
             O SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
               (DIMER DIOL)) (3A) ?ACRYL?)
             5 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L26
               (DIMER DIOL)) (3A) ?ACRYL?)
            19 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L27
               (DIMER DIOL)) (3A) ?ACRYL?)
            13 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
L28
               (DIMER DIOL)) (3A) ?ACRYL?)
    TOTAL FOR ALL FILES
L29
            68 SEA SPE=ON ABB=ON PLU=ON ((DIMERDIOL OR DIMER-DIOL OR
               (DIMER DIOL)) (3A) ?ACRYL?)
L30
            31 SEA SPE=ON ABB=ON PLU=ON L24 AND (COAT? OR APPL?)
L31
             O SEA SPE=ON ABB=ON PLU=ON L25 AND (COAT? OR APPL?)
L32
             5 SEA SPE=ON ABB=ON PLU=ON L26 AND (COAT? OR APPL?)
L33
            18 SEA SPE=ON ABB=ON PLU=ON L27 AND (COAT? OR APPL?)
            13 SEA SPE=ON ABB=ON PLU=ON L28 AND (COAT? OR APPL?)
L34
    TOTAL FOR ALL FILES
            67 SEA SPE=ON ABB=ON PLU=ON L29 AND (COAT? OR APPL?)
L35
             2 SEA SPE=ON ABB=ON PLU=ON L24 AND (FLATTING OR FLATTED OR
L36
               MATTE OR MATTED OR MATTING)
             O SEA SPE=ON ABB=ON PLU=ON L25 AND (FLATTING OR FLATTED OR
L37
               MATTE OR MATTED OR MATTING)
             O SEA SPE=ON ABB=ON PLU=ON L26 AND (FLATTING OR FLATTED OR
L38
               MATTE OR MATTED OR MATTING)
             1 SEA SPE=ON ABB=ON PLU=ON L27 AND (FLATTING OR FLATTED OR
L39
               MATTE OR MATTED OR MATTING)
L40
             1 SEA SPE=ON ABB=ON PLU=ON L28 AND (FLATTING OR FLATTED OR
               MATTE OR MATTED OR MATTING)
    TOTAL FOR ALL FILES
L41
             4 SEA SPE=ON ABB=ON PLU=ON L29 AND (FLATTING OR FLATTED OR
               MATTE OR MATTED OR MATTING)
               D 1-4 BIB AB KWIC
            29 SEA SPE=ON ABB=ON PLU=ON L30 AND GLASS
L42
L43
            O SEA SPE=ON ABB=ON PLU=ON L31 AND GLASS
```

L44 L45 L46	4 14 7		PE=ON	ABB=ON ABB=ON ABB=ON	PLU=ON PLU=ON PLU=ON	L33		GLASS GLASS GLASS
	TOTAL FOR	ALL FI	LES					0
L47	54	SEA S	PE=ON	ABB=ON	PLU=ON	L35	AND	GLASS
L48	54 DUP REM L47 (0 DUPLICATES REMOVED)							
		D 1-5	4 BIB 2	AB KWIC				
	D 1-54 BIB AB							
D 1-54 BIB AB KWIC								
L49	2	SEA S	PE=ON	ABB=ON	PLU=ON	L24	AND	FLAT
L50	0	SEA S	PE=ON	ABB=ON	PLU=ON	L25	AND	FLAT
L51	0	SEA S	PE=ON	ABB=ON	PLU=ON	L26	AND	FLAT
L52	1	SEA S	PE=ON	ABB=ON	PLU=ON	L27	AND	FLAT
L53	0	SEA S	PE=ON	ABB=ON	PLU=ON	L28	AND	FLAT
	TOTAL FOR	ALL FI	LES					
L54	3	SEA S	PE=ON	ABB=ON	PLU=ON	L29	AND	FLAT
D 1-3 BIB AB KWIC								